

Factory-Authorized  
Service Center



# Autopilot System Capabilities

## KFC-200 Autopilot Systems

KA 285	KG 102A	KI 254
KA 51B	KG 107	KI 255
KAS 297/A	KG 257	KI 256
KC 290	KG 258	KI 525A
KC 295	KG 259	KRG 331
KC 296	KI 254	



KI 525A

**Mid-Continent Instruments and Avionics offers comprehensive maintenance, repair, overhaul, and exchange services for BendixKing KI 525A Pictorial Navigation Indicators.**

We deliver quick turns and offer an extensive exchange pool. Utilizing only BendixKing authorized parts, our expert technicians rebuild your unit to perform like new, including a complete update to current MOD status.



Factory-Authorized Service Center

# Autopilot System Capabilities

Comprehensive maintenance, repair, overhaul, and exchange services for BendixKing KG 102A Directional Gyros.



KG 102A

Quick turn

Expert technicians with more than 20 years of experience

Extensive exchange pool

BendixKing authorized parts

Comprehensive overhaul and repair

Service bulletin upgrades

Hot and cold chamber testing

All gyro rotors replaced during overhaul (48 hr. run-in and re-test to eliminate cold-start problems)

