

# MID-CONTINENT INSTRUMENT CO., INC.

WICHITA, KS

## Service Bulletin & Service Information Letter Index

<u>PART NUMBER</u>	<u>NOMENCLATURE</u>	<u>PUB NUMBER</u>	<u>REVISION-DATE</u>
1394T100-B	TURN COORDINATOR	SIL-1394T100-B	5/30/06
1394T100-( )RB	TURN COORDINATOR	SB-1394T100-( )RB-01	8/29/07
1394T100-10RA	TURN COORDINATOR	SB-1394T100-10RA-01	5/30/01
1394T100-10RZ-A	TURN COORDINATOR	SB-1394T100-10RZ-A	8/4/99
1394T100-14RB	TURN COORDINATOR	SB-1394T100-14RB-A	5/24/07
3300-XX Series	DIRECTIONAL GYRO	SIL-01-3300-XX	7/8/08
4200-XX Series	ATTITUDE INDICATOR, 2"	SB-4200-XX-01 SB-4200-XX-02	9/26/06 2/1/08
4300-XXX Series	ATTITUDE INDICATOR MOD 1 ATTITUDE INDICATOR MOD 2 ATTITUDE INDICATOR MOD 3 ATTITUDE INDICATOR MOD 4 ATTITUDE INDICATOR	SB-4300-XXX-01 SB-4300-XXX-02 SB-4300-XXX-03 SB-4300-XXX-04 SIL-01-4300-XXX SIL-02-4300-XXX SIL-03-4300-XXX SIL-04-4300-XXX SIL-05-4300-XXX SIL-06-4300-XXX	9/12/05 9/12/05 9/12/05 12/31/07 10/26/05 8/30/06 11/29/06 1/2/07 6/06/08 7/30/09
4300-8765-( )L	ATTITUDE INDICATOR	SIL-01-4300-8765-( )L	10/08/08
4305-150	DIRECTIONAL GYRO	SB-4305-150-01 SB-4305-150-02 SB-4305-150-03 SIL-01-4305-150	8/1/01 12/18/01 9/2/02 4/3/02
MD200 SERIES	COURSE DEVIATION INDICATOR, 2"	SB-MD200-SERIES-01 SIL-MD200-SERIES-01	12/20/99 5/30/01
MD200-4XX,-5XX	COURSE DEVIATION INDICATOR, 2"	SIL-01-MD200-4XX,5XX	5/15/07
MD421-01	BATTERY MODULE	SB-MD421-01	12/1/08